



1

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN MILLIMETERS DECIMALS ANGLES X.X = 0.3 X .5 X.XX = 0.15 X.X .1 ALL MACH SURFACES 3.2 ✓				FINISH:		DEBUR AND BREAK SHARP EDGES		DO NOT SCALE DRAWING		REVISION C	
								CLAMP ALL			
	NAME		SIGNATURE		DATE				TITLE: CLAMP, RIGHT BOTTOM		
DRAWN	DWT				15 01 27						
CHK'D	PJS				15 01 30						
APPV'D	JDR				15 02 02						
MFG	JVP				15 02 01						
Q.A	MDR				15 02 01		MATERIAL:		DWG NO.		SW-43567-101
							6061-T6 (SS)				
											A3
							WEIGHT: 158.9268		SCALE:1:1		SHEET 1 OF 1



1

NOTES:

1. FINISH ALL OVER
2. BREAK SHARP EDGES TO 0.01 MAX
3. ALL SURFACES MUST BE FREE OF BURRS
4. SANDBLAST BEFORE PAINTING
5. APPLY THREE COATS PAINT

2

1